



Guardrail is in the way.
Traffic from driveway has to
pull into oncoming lane to
turn right onto highway (MP 4.5)

Speed limit reduction should
extend to MP 3.5

MP 2.5 to 3.5:
Children playing in area.
Speeding traffic
Need School Bus Stop sign at MP 3.
Need room for school bus turnaround.

Poor sight distance from
Murray Rd (MP 3.33)

Need pullout for passing at MP 3

Narrow bridge at Coal Creek (MP 2.65).
Water collects on northbound lane.

MP 2.5 to 3.5:
Houses close to highway.
Residences must back out of driveways
directly onto highway.
Poor sight distance from driveways due to
parked cars and shrubs.
Should be No Passing Zone.

MP 2.5:
Narrow bridge with curve.
Known as "Head-on Collision Bridge"

MP 2:
Need guardrail.
Shady and icy.

Speed reduction should
be extended to MP 2

No warning sign of
approaching speed reduction

Legend

- State Routes
- Mileposts
- Streams/Rivers

0 250 500 1,000 1,500 2,000
Feet

WSDOT SR 7 Route Development Plan Likes/Dislikes MP 2 to 5